



RAK PORTS
Doc. No. RP ISP 011-32-A
Rev. Orig. Issue Date: 12/11/2016

AI JAZEERA PORT DAILY PORT POSITION

Date	:	12.05.2023	Time	:	0700 HRS
Tide	:	2.21-0324/0.72-1106/1.87-1725/1.34-2244			
Warnings	:	NIL			
Weather	:	Dry			
Visibility	:	4-8 KM			
Lightning Risk	:	NIL			
Fog Risk	:	NIL			
Wind	:	Max Sustained Wind (Ws10) 10 Knots			
Sea Waves	:	Max Significant Wave Height (Hs): 0.40M			
Temperature(Max)	:	30°C			
Temperature(Min)	:	26°C			
Sun Rise	:	05:33 Hrs.			
Sun Set	:	18:53 Hrs.			

EXPECTED								
Date	Time	Vessel Name	Flag	LOA (M)	GRT (Tons)	Draft (M)	Agent	Remarks
TBA	TBA	T-Jaywun	UAE	47.10	1250	TBC	GAC RAK	For Clearance
TBA	TBA	T-Pacific Vortex	British	31.00	476	TBC	GACRAK	Towing B-S 46
		B-S 46	Bahamas	91.50	3880	TBC	GAC RAK	For Repair
ANCHORAGE								
Date	Time	Vessel Name	Flag	LOA (M)	GRT (Tons)	Draft (M)	Agent	Remarks
12.05.23	0600	T-Lanpan 22	Singapore	35.42	488	3.80	RAK Ports SCS LLC	Towing B-JMC 2600
		B-JMC 2600	USA	82.00	2402	2.00	RAK Ports SCS LLC	For Repair
BERTH								



RAK PORTS
Doc. No. RP ISP 011-32-A
Rev. Orig. Issue Date: 12/11/2016

AI JAZEERA PORT DAILY PORT POSITION

Berth	Date	Time	Vessel Name	Flag	LOA (M)	GRT (Tons)	Sail Draft	Agent	Remarks
B-1	03.02.22	1540	T-Zaini	St. Kitts	31.00	471	2.00	WWSL	Under Repair
	07.04.15	0750	T-Dubai Water <i>(Ex-Aqua Sea)</i>	UAE	14.91	22	1.00	RAK Ports SCS LLC	Under Repair
	05.10.19	1100	T-Dubai Dream <i>(Ex-Al Hamra 102)</i>	UAE	12.50	15	1.00	RAK Ports SCS LLC	Under Repair
	25.06.18	1445	T-Jazira 2 <i>(Ex-Smit Kubbar)</i>	St. Vincent	23.50	74	2.00	RAK Ports SCS LLC	Under Repair
	25.10.22	1100	T-Al Danah 2	UAE	---	---	---	---	New Build
B-2	23.06.21	1450	T-Masafi	UAE	17.50	55.17	2.50	RAK Ports SCS LLC	AJZP Assisting Tug
	23.06.21	1500	T-Ghalilah	UAE	15.70	57	2.00	RAK Ports SCS LLC	AJZP Assisting Tug
	24.12.22	1140	T-SL Hodeidah	Liberia	33.31	724	6.10	RAK Ports SCS LLC	Lay Up
	25.04.23	0915	T-SL Sokol	Liberia	25.78	253	4.50	RAK Ports SCS LLC	Under Repair
	24.02.23	1115	T-Affinity	Palau	29.61	299	2.50	RAK Ports SCS LLC	Under Repair
	29.04.23	1700	T-Akshant	Panama	28.06	270	3.00	RAK Ports SCS LLC	Lay Up
	22.11.22	1210	T-Hulaylah	UAE	19.50	55.17	2.50	RAK Ports SCS LLC	AJZP Assisting Tug
B-3									Vacant
B-4	23.08.22	1300	T-Aqua Rise III	Panama	32.12	1967	2.50	RAK Ports SCS LLC	Under Repair
	10.10.21	1010	B-CMT 1	Panama	86.30	6036	4.10	GAC RAK	Under Repair
	11.02.23	1445	B-Kunming	Palau	106.75	5793	1.00	RAK Ports SCS LLC	Under Repair
	08.04.23	1515	Lanpan CB 6	Singapore	105.41	6635	1.50	RAK Ports SCS LLC	Under Repair
	12.02.23	1415	B-Lanpan CB 8	Singapore	105.41	6635	1.00	RAK Ports SCS LLC	Under Repair
B-5	05.05.23	1110	B-Astro 3302	Singapore	96.56	4948	1.20	RAK Ports SCS LLC	Under Repair
B-6	11.05.23	0530	SV-Bourbon Liberty 318	ST. Vincent	65.75	2245	4.40	RAK Ports SCS LLC	ENI BV RAK Project
B-7	11.05.23	1715	SV-Bourbon Calima	ST. Vincent	55.10	499	2.50	RAK Ports SCS LLC	ENI BV RAK Project



RAK PORTS
Doc. No. RP ISP 011-32-A
Rev. Orig. Issue Date: 12/11/2016

AI JAZEERA PORT DAILY PORT POSITION

B-8	11.05.23	1015	T-Hani 30	Iran	32.10	299	3.20	AGT	Towing B-Baran 110
			B-Baran 110	Iran	91.44	2962	4.40	AGT	Disch.6520MT Feldspar
B-9	02.01.23	0900	B-JMC 3332	USA	87.84	3956	1.20	RAK Ports SCS LLC	Under Repair
	09.05.22	1200	B-Pinocchio	Belgium	57.60	1040	3.20	RAK Ports SCS LLC	Lay-Up
	05.03.21	1450	B-PDC 2	Belgium	61.45	1242	2.20	RAK Ports SCS LLC	Lay-Up
	20.03.08	1330	T-AI Hamra 1	UAE	12.65	20	1.00	RAK Ports SCS LLC	AJZP Transportation/Pilot Boat
RAMP 1									
RAMP 2									
Ramp damaged not able to use required to install bollard									
RAMP 3									
Ramp damaged not able to use required to install bollard									
RAMP 4									
Ramp damaged not able to use required to install bollard									
DRY-DOCKED									
Berth	Docking		Undocking	Vessel Name	Flag	LOA	Agent	Remarks	
	Date	Time	Expected Date						
DD YARD	---	---	---	MY-RP 681	---	---	---	Under Repair	
B-1	-----	-----	-----	Seagate Shipyard	-----	-----	-----	Ship Under Construction	
B-2	07.03.23	1120	(17.05.23)	T-Maftoon	St. Kitts	29.00	RAK Ports SCS LLC	Under Repair	
	06.09.22	0900	TBA	T-SL Kittiwake	Singapore	20.41	RAK Ports SCS LLC	Lay Up	
B-3	09.05.23	1310	(15.05.23)	T-MCS Allianz Coromell	Panama	23.98	RAK Ports SCS LLC	Under Repair	
B-4	10.05.23	1340	(19.05.23)	T-MCS Zephyr	UK	19.08	RAK Ports SCS LLC	Under Repair	
B-5								Vacant	
B-6				Mark Marine	-----	-----	-----	Ship Under Construction	



RAK PORTS
Doc. No. RP ISP 011-32-A
Rev. Orig. Issue Date: 12/11/2016

AI JAZEERA PORT DAILY PORT POSITION

B-7	-----	-----	-----	Mark Marine	-----	-----	-----	Ship Under Construction
B-8	-----	-----	-----	Mark Marine	-----	-----	-----	Ship Under Construction
B-9	-----	-----	-----	Catamaran	-----	-----	-----	Ship Under Construction
B-10	-----	-----	-----	Catamaran	-----	-----	-----	Ship Under Construction
B -11	25.07.22	0900	TBA	T-SL Kestrel	Singapore	21.50	RAK Ports SCS LLC	Lay Up
	05.07.22	1605	TBA	T-SL Kite	Singapore	21.50	RAK Ports SCS LLC	Lay Up
	05.07.22	1120	TBA	SBM Mono Buoy	--	--	RAK Ports SCS LLC	Lay Up
	16.08.22	0940	TBA	T-SL Nisr	Cyprus	19.00	RAK Ports SCS LLC	Lay Up
B-12	28.02.22	0915	TBA	Neptune Hotel	UAE	---	---	New Build
	28.04.22	1150	(15.05.23)	T-AST 26	UAE	17.63	Corporate Shipping	Under Repair
	23.09.22	1015	TBA	T-SL Madagascar	Cyprus	25.92	RAK Ports SCS LLC	Lay Up

Prepared By: Port Controller

Name: Mayolin Agliam Agarano

Approved By : Operation Supervisor

Name : Mr. Sathak Hussain