



NOTICE TO MARINERS

No. 02 – 15th Feb 2022

Sub: Change of RMC Beacon Characteristics

Ref: BA Chart 3404 & 3174

Please be notified that characteristics of beacon fixed at the RMC breakwater has been changed as follows :

Beacon	Colour	Flash Characteristic	Position of Beacon		Remarks
RMC Beacon	White	Fl.3s4m2M	25° 58.022'N	056° 02.835'E	Colour changed to 'White'

Mariners are requested to update respective BA charts.

Capt. Emadeldin Hashem

Deputy Harbour Master, RAK Ports

Status of previously published notices:

2022: 01

2020 : 01, 2021: 01, 11, 14, 20, 21