



# **NOTICE TO MARINERS**

**No. 15– 13<sup>th</sup> July 2021**

**Sub: Re-positioning of Al Jazeera Port Outer Channel Buoys**

Ref: BA Chart 3174, 3404 & attached Chartlet 3404

Please be notified the Outer Channel Light Buoys in the approaches to Al Jazeera Port have been re-positioned to below mentioned coordinates. Chartlet indicating the position of buoys is attached herewith.

The characteristics of buoys will remain unchanged.

Buoy Name	Characteristic	New Position Coordinates	
Fairway Buoy	LFl.10s	25° 44.994'N	55° 46.730'E
Outer No.1	Fl.G.6s	25° 44.299'N	55° 47.409'E
Outer No.2	Fl.R.3s	25° 44.422'N	55° 47.538'E
Outer No.3	Fl.G.3s	25° 43.843'N	55° 47.944'E
Outer No.4	Fl.R.6s	25° 43.966'N	55° 48.072'E

All Mariners are advised to update their charts.

**Capt. Emad Hashem**

Deputy Harbour Master, RAK Ports

*Status of previously published notices:*

2020: 01, 04, 07, 09, 16

2021: 01, 03, 07, 10, 11, 13, 14

